



APD Noise on the Far Detector

R.J. Tesarek
7/16/13



The Problem




What we've seen

- ~1 di-block (768) APDs installed before 5/20 have initial and continued performance good
- ~1 di-block (768) APDs installed after 5/20 following same installation and checkout procedures show:
 - ➡ Pass QA tests prior to installation
 - ➡ Higher hit rates (noise) at the nominal bias voltage
 - ➡ Higher readout threshold
 - ➡ Larger and increasing data rates
- “Training” APDs with high hit rates appears to help (not understood)
- APD “training”:
 1. Start with lower bias voltage (300V)
 2. Hold until data rates stabilize
 3. Raise bias voltage 25V and repeat 2. above until nominal bias voltage achieved
- ➡ We do not understand the need for training some of the APDs, what changed to cause this or the long term effects


Nominal APD Conditions:

- Water cooled ($T \sim 60^\circ\text{F}$)
- Supply voltage 425V regulated down to 350V (APD bias voltage)
- Dew point in dry gas branches $< -30^\circ\text{C}$
- Readout thresholds 50-60 ADC counts
- Parylene coating thickness 0.0004” - 0.0006”



Pixel Readout Thresholds


Pixel Thresholds 2013-06-28_12_01_15



Note: each black box represents 64 APDs (2048 channels)



Noise Example





NOvA - FNAL E929

Run: 10537 / 0

Event: 6635 / CAL

UTC Thu Jul 4, 2013

08:59:48.412835008



Note: Each green box above represents 64 APDs installed (2048 detector channels)



Evidence that training works




FEBs installed

FEBs & APDs installed

Detector Top

Detector Side





What We Know So Far



Held meeting on 6/11 to discuss strategy/avenues to explore to understand the issue (experts only)

Additional meeting held 7/10 including experts spokespersons, PPD, directorate

What we've learned, improved/ruled out

- Installation at Ash River “unchanged”. Handling/testing procedures tightened.
- No position or installer dependence
- Noise not from FEBs (see slide 4)
- Mechanical tolerances unlikely (QA at Ash River/ observations of removed devices)
- Reduced susceptibility of QA equipment to humidity at Ash River
- Short term tests at CalTech/Ash River do not show problems (tests last minutes)
- Noise shows up only after biased for some time (hrs)

Test Parts from Ash River

- Failed QA (heat sink seal, bad hoses)
- Noisiest parts removed from far detector



APD Tests at CalTech





Monitor bias current for longer periods than typical QA tests.

NOTE: Vertical scale changes from plot to plot



Random APDs from Ash River (2 hr test)

Uncoated Hamamatsu APDs (12 hr test)



Noisy APDs removed from detector (2 hr test)

Batch 10 Parylene Coated Parts (12 hr test)





Conclusions to Date

Qualitatively reproduce the observations on the far detector:

- Short term (QA) tests show no problem
- Problem manifests after some time
- Time on bias voltage decreases current (training)

Additional observations:

- Recently coated (batch 10) show similar problem features to that seen in noisy APDs from the detector
- APDs sitting on shelf at Advanced Coatings behave as new APDs from Hamamatsu
- APDs baked by Advanced Coatings behave as new APDs from Hamamatsu
- Evidence that power cycling a trained APD does not return that APD to a noisy state

Plans

- Additional bench tests at CalTech
- Develop sharper tools to measure pixel rates (Indiana, Minnesota)
- Add P.Rubinov, A.Rhonzhin, (FNAL/PPD) to help perform tests at FNAL
- Install parts on near detector test stand to understand performance of cold APDs
- Work with coater to better understand processing
- B.Flaugher, P.Rubinov, T.J.Sarlina to visit CalTech/Advanced coatings to review APD processing
- Operate APDs with nominal gain (100) and cold (-15C) and monitor performance






Back Up Slides





Fingerprints Observed at A.R.




Gloves required for all APD handling
at CalTech/Ash River



APD Mechanical Tolerances

Note: ~4% of the optical connectors are measured at Ash River. All are within tolerance
(data in NOvA-doc-7469)

APD Back-off from Optical Bosses




- Carrier Board thickness: 0.0622" +/- 0.0021"
(NOVA-DOC-6412, NDOS)
- Parylene Coating: 0.00045" +/- 0.00007"
(Email from Leon)
- Glue: 0.0032" +/- 0.0024"
(NOVA-DOC-6412, NDOS)
- Built-in "Shim": 0.0059" +/- 0.00197"/0"
(NOVA-DOC-6346)
- PCB back to APD (Gold Bump): ~0.00335" +/- ??(0.00004)
(NOVA-DOC-6474)

Optical boss to coating surface (OBCS) = Shim + Bump – Glue – 2*coating
(Note: The glue shouldn't add to the calculation if contained to glue channel)
OBCS Value with no glue: 0.00825" +/- 0.002"/0.0002"
OBCS Value with glue: 0.0052" +/- 0.003"/0.0024"

Conclusion: If the parts are in spec, mechanical interference is highly unlikely.
(Do we have recent measurements of the part dimensions?)




Uncoated Parts from Coater



Sample of 1st 14 look perfect in 8 hr test


Instrumentation problem in 3rd plot top row

Performance similar to Hamamatsu uncoated parts






Uncoated Parts from Early Coating Batches



All show high early currents that decay away

Several $> 1 \mu\text{A}$, several $> 100 \text{nA}$






Power Cycle Tests



Test parts over 8 hrs.

Power down for several hours

Re-test for 2 hrs



Lower amplitude
transient in
2nd test